

City of Santa Fe Fire Department RECORD OF FIRE INSPECTION

No. 07329

Property Name _____ Building Location 2501 Rodeo Rd
Common Name Joe's Diner Date 11/18/19
Contact Robund Phone 471-3800
Inspected By Jennifer Dickey

BUILDING INFORMATION

Occupancy type: A-2 District: 7 No. of floors: 1 Detector type: N/A
Complex type: SM Fixed property: Fix No. of sub-floors: 0 Detector power supply: _____
Property status: Occ Structure type: _____ Number of units: _____

VIOLATIONS

- Shall repair smoke detector(s) as per the 2009 IFC.
- Shall re-service fire extinguisher(s) annually as required by NFPA 10 and per the 2009 IFC.
- Shall repair exit sign(s) to operate in both normal and emergency modes as per the 2009 IFC.
- Shall provide and mount approved fire extinguisher(s) in visible and accessible area(s) between 3 & 5 ft. from the finished floor as per the 2009 IFC.
- Electrical breaker panel(s) shall be properly labeled as per the 2009 IFC.
- Shall provide blank cover(s) for any missing knock-out(s) for the electrical breaker panel as per the 2009 IFC.

No Violations Found @ This Time

Madeira Taylor

Type of Inspection:

- Home Occupancy Inspection
- Special Event Inspection
- Tent(s)/Canopy
- Kiosk
- Special Use Inspection
- Vendor/Cart
- Other Annual
- Re-inspection _____